#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-021929

Address: 333 Burma Road **Date Inspected:** 15-Mar-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

**CWI Name:** See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

**Bridge No:** 34-0006 **Component:** OBG

#### **Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector Brett W Rice was present during the times noted above for observations relative to the work being performed at ZPMC.

Bay 14 East

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Cored Arc Welding (FCAW) process.

ZPMC QC is identified as Zhong Yong Gang.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

PCMK: SEG-3019\* Weld No: 166 Welder: 055491

WPS-B-T-2232-ESAB

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Zhong Yong Gang.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

# WELDING INSPECTION REPORT

(Continued Page 2 of 4)

PCMK: SEG-3019BB

Weld No: 171 Welder: 215553

WPS-B-P-2212-TC-U4b-FCM-1

PCMK: SEG-3019BB

Weld No: 105 Welder: 216086

WPS-B-P-2212-TC-U4b-FCM-1

PCMK: SEG-3019AB

Weld No: 136 WR: 20369 Welder: 044779

WPS-345-SMAW-4G(4F)-FCM-Repair-1

PCMK: SEG-3019X Weld No: 008 and 009

WR: 20361 Welder: 054013

WPS-345-SMAW-4G(4F)-FCM-Repair-1

Bay 14 (NDT)

Deck Panel; QAUT per ZPMC NDT Inspection Notification doc. #08553 Item 1. Welds identified as: DP3172-001-017~021 and DP3173-001-020~024

Bay 16

This QA Inspector observed the following work in progress for Bay 16.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Yang Yi Heng.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS). Listed below are the locations that were identified by this QA inspector.

PCMK: W5-SB30-002

Weld No: 114, 046, and 047

Welder: 053753 WPS-B-P-2113

PCMK: E2-SB23-002

Weld No: 079 Welder: 053753 WPS-B-P-2113

PCMK: E5-SB29-001

# WELDING INSPECTION REPORT

(Continued Page 3 of 4)

Weld No: 017, 018, 048, and 049

Welder: 201861 WPS-B-P-2113

PCMK: W2-SB20A-001

Weld No: 048, 049, 079 and 080

Welder: 201905 WPS-B-P-2113

This QA Inspector observed the following work in progress for Bay 16.

ZPMC was using the Flux Cored Arc Welding (FCAW) process.

ZPMC QC is identified as Yang Yi Heng.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

PCMK: E5-SB25C-005 Weld No: 126~131 Welder: 048625 WPS-2132-ESAB

PCMK: E2-SB26A-001 Weld No: 126~131 Welder: 222396 WPS-2132-ESAB

PCMK: W5-SB37-001

Weld No: 020 Welder: 222396 WPS-2132-ESAB

PCMK: W5-SB36-001 Weld No: 126~131 Welder: 053742 WPS-2132-ESAB

PCMK: W5-SB30-001 Weld No: 126~131 Welder: 222396 WPS-2132-ESAB

PCMK: W5-SB41C-001

Weld No: 122 Welder: 201074

WPS-B-T-2132-ESAB

# WELDING INSPECTION REPORT

(Continued Page 4 of 4)

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.





## **Summary of Conversations:**

No relevant conversations were reported on this date.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Rice,Brett	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer